Material Safety Data Sheet INTERSTORES POLYURETHANE TOPCOAT GREEN PART A

Bulk Sales Reference No.: MSDS Revision Date:

MSDS Revision Number:

Sales Order: {SalesOrd} ISA230 02/13/2013 A0-

XInternational.

1. Identification of the preparation and company

Product Identity

Bulk Sales Reference No. Company Name INTERSTORES POLYURETHANE TOPCOAT GREEN PART A ISA230 International Paint LLC 6001 Antoine Drive Houston, Texas 77091

Emergency
CHEMTREC (USA)
International Paint
Poison Control Center
Customer Service
International Paint
Fax No.

(713) 682–1711 (800) 854–6813 (800) 589–1267 (800) 631–7481

(800) 424-9300

2. Hazard identification of the product



Warning

Item	Category	Hazard
Flammability	3	Flammable liquid and vapor
Acute Toxicity (mouth)	Not classified	Not applicable
Acute Toxicity (skin)	Not classified	Not applicable
Acute Toxicity (inhalation)	Not classified	Not applicable
Acute Toxicity (ingestion)	Not classified	Not applicable
Skin corrosion/irritation	2	Causes skin irritation
Eye damage/irritation	2A	Causes serious eye irritation
Sensitization (respiratory)	Not classified	Not applicable
Sensitization (skin)	Not classified	Not applicable
Germ toxicity	Not classified	Not applicable
Specific target organ systemic toxicity (single exposure)	1	central nerve system, kidneys, liver, respiratory system
	2	central nerve system
	3	Not applicable
Specific target organ systemic Toxicity (repeated exposure)	1	central nerve system, respiratory system
	2	Not applicable
Aspiration hazard	1	Known to cause human aspiration toxicity hazards
Harmfulness to aquatic Environment (acute)	3	Harmful to aquatic life.
	4	

Harmfulness to aquatic Environment (long term effect)		May cause harm to aquatic life with long lasting effects
Carcinogenicity	Not classified	Not applicable
Reproductive Toxicity	Not classified	Not applicable
Organic Peroxide	Not classified	Not applicable

Safety Phrases:

S1: Keep locked up.

S23: Do not breathe vapor/spray.

S26: In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

S27: Take off immediately all contaminated clothing.

S28: After contact with skin, wash immediately with plenty of soap and water.

S36/37: Wear suitable protective clothing and gloves.

S39: Wear eye/face protection.

S45: In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).

S46: If swallowed, seek medical advice immediately and show this container or label.

S51: Use only in well-ventilated areas.

S61: Avoid release to the environment. Refer to special instructions/Safety data sheets.

S62: If swallowed, do not induce vomiting: seek medical advice immediately and show this container or label.

Overview	NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal. Avoid contact with eves, skin and clothing.				
Inhalation	Harmful if inhaled. Caus may affect the brain or n	0			
Eyes	Risk of serious damage selected to provide prote this document. Dependin chemical goggles, and/o contact. The equipment	ection from exposure to ng on the site-specific c or head and face protect	the chemicals listed in ondition of use, safet ion may be required t	n Section 3 of y glasses, o prevent	
Skin	Causes skin irritation. M through the skin.	ay cause delayed skin i	rritation. May be harm	nful if absorbed	
Ingestion	Harmful if swallowed. Ma drowsiness.	ay cause abdominal pai	n, nausea, vomiting, o	diarrhea, or	
Chronic effects	Possible cancer hazard. animal data (See Sectio depends on duration and	n 2 and Section 15 for e			
HMIS Rating	Health: 2*	Flammability: 3	Reactivity: 0	PPE: X	

3. Composition/information on ingredients				
Ingredient	CAS No.	Percent		
1,2,4–Trimethyl benzene	0000095-63-6	1.0 – 10		
Benzene, ethyl-	0000100-41-4	1.0 – 10		
Propylene glycol monomethyl ether acetate	0000108-65-6	1.0 – 10		
Limestone	0001317-65-3	10 – 25		
Xylenes (o–, m–, p– isomers)	0001330-20-7	10 – 25		
Barium sulfate	0007727-43-7	10 – 25		
Quartz	0014808-60-7	0.10 - 1.0		
Petroleum naphtha	0064742-95-6	10 – 25		
This product contains 0.12 percent Quartz.				

4. First aid measures

General

Ingestion If swallowed, immediately. contact Poison Control Center at 1-800-854-8613. DO NOT induce vomiting unless instructed to do so by medical personnel. Never give anything by mouth to an unconscious person. 5. Fire-fighting measures Flash Point F: 93 C: 34 Lower Explosive Limit (LEL) .19 (%vol in air) at Normal Atmospheric Temp and Pressure ERG Guide No. 128 Spill Response ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foarn may be used to reduce vapors. Absorb or over with dry earth, sand, or other non-combustible material and tasofored. Do not buse thor emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 Public Safety CALL CHEMTREC at (800)-424–9300 for emergency response. Isolate spill or leak are immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized		Remove contaminated clothing and shoes. Get medical attention immediately. Wash clothing before reuse. Thoroughly clean or destroy contaminated shoes.		
15 minutes. Get medical attention immediately. Skin In case of contact, immediately flush skin with soap and plenty of water. Get medical attention immediately contact Poison Control Center at 1-800-854-6813. DO NOT induce vomiting unless instructed to do so by medical personnel. Never give anything by mouth to an unconscious person. Image: State	Inhalation			
Ingestion If swallowed, immediately, contact Poison Control Center at 1+800-854-6813. DO NOT induce vomiting unless instructed to do so by medical personnel. Never give anything by mouth to an unconscious person. 5. Fire-fighting measures Flash Point F: 93 C: 34 Lower Explosive Limit (LEL) .19 (%vol in air) at Normal Atmospheric Temp and Pressure ERG Guide No. 128 Spill Response ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and ransfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in ail directions. Keep unauthorize entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 Thandling and Storage 7. Handling and storage Storage Temperature	Eyes	In case of contact, immediately flush eyes with plenty of water for at least		
1-800-854-8513. DO NOT induce vomiting unless instructed to do so by medical personnel. Never give anything by mouth to an unconscious person. Image: Second Seco	Skin	In case of contact, immediately flush skin with soap and plenty of water. Get medical attention immediately.		
Flash Point F: 93 C: 34 Lower Explosive Limit (LEL) .19 (%vol in air) at Normal Atmospheric Temp and Pressure ERG Guide No. ERG Guide No. 128 6. Accidental release measures Spill Response Procedures ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 7. Handling and storage Precautions Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and othe sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clothing. Close container a	Ingestion	1–800–854–6813. DO NOT induce vomiting unless instructed to do so by medical personnel. Never give anything by mouth to an unconscious		
C: 34 Lower Explosive Limit (LEL) . 19 (%vol in air) at Normal Atmospheric Temp and Pressure ERG Guide No. 128 Spill Response Procedures ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electic motors and other sources of ignition during use and until all vapors are gone. Vapors may cuse flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.		5. Fire-fighting measures		
ERG Guide No. 128 6. Accidental release measures Spill Response Procedures ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 7. Handling and storage Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.	Flash Point			
6. Accidental release measures Spill Response Procedures ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 7. Handling and storage Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and othe sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.	•			
Spill Response ELIMINATE ALL IGNITION SOURCES (no smoking, flares, sparks or flames in immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 Storage Temperature Handling and Storage Store between 40-100F (4-38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clohing. Close container after each use. Wash thoroughly after handling.	ERG Guide No.	120		
Procedures immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use non-sparking tools to collect absorbed material. Public Safety CALL CHEMTREC at (800)-424-9300 for emergency response. Isolate spill or leak area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 Zerge Temperature Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.		6. Accidental release measures		
area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300 meters (1000 feet). ERG Guide No. 128 7. Handling and storage Storage Temperature Handling and Storage Precautions Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.		immediate area). Use only non-sparking equipment to handle spilled material and absorbent. Do not touch or walk through spilled material. Stop leak if you can do so without risk. Prevent entry into waterways, sewers, basements or confined areas. A vapor suppressing foam may be used to reduce vapors. Absorb or cover with dry earth, sand, or other non-combustible material and transfer to containers. Use		
7. Handling and storage Storage Temperature Handling and Storage Precautions Store between 40–100F (4–38C). Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.	Public Safety	area immediately for at least 50 meters (150 feet) in all directions. Keep unauthorized personnel away. Stay upwind. Keep out of low areas. Ventilate closed spaces before entering. LARGE SPILLS: Consider initial downwind evacuation for at least 300		
Storage Temperature Store between 40–100F (4–38C). Handling and Storage Keep away from heat, sparks and flame. Do not smoke. Extinguish all Precautions flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.	ERG Guide No.	128		
Storage Temperature Store between 40–100F (4–38C). Handling and Storage Keep away from heat, sparks and flame. Do not smoke. Extinguish all Precautions flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.		7. Handling and storage		
Handling and Storage Precautions Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after handling.	Storago Tomporaturo	Store between 40, $100E(4, 28C)$		
8. Exposure controls and personal protection	Handling and Storage	Keep away from heat, sparks and flame. Do not smoke. Extinguish all flames and pilot lights, and turn off stoves, heaters, electric motors and other sources of ignition during use and until all vapors are gone. Vapors may cause flash fire or ignite explosively. Prevent build–up of vapors by opening all windows and doors to achieve cross–ventilation. Do not get in eyes, on skin or clothing. Close container after each use. Wash thoroughly after		
		8. Exposure controls and personal protection		

	Exposure		
CAS No.	Ingredient	Source	Value
0000095–63–6	1,2,4–Trimethyl benzene	OSHA	No Established Limit
		ACGIH	No Established Limit
		NIOSH	25 ppm TWA; 125 mg/m3 TWA
		Supplier	No Established Limit
		OHSA, CAN	No Established Limit
		Mexico	No Established Limit
		Brazil	No Established Limit
0000100-41-4 Benzene, ethyl-		OSHA	

			100 ppm TWA; 435 mg/m3 TWA125 ppm STEL; 545 mg/m3 STEL
		ACGIH	100 ppm TWA125 ppm STEL
		NIOSH	100 ppm TWA; 435 mg/m3 TWA125 ppm STEL; 545 mg/m3 STEL800 ppm IDLH (10% LEL)
		Supplier	No Established Limit
		OHSA, CAN	100 ppm TWA125 ppm STEL
		Mexico	100 ppm TWA; 435 mg/m3 TWA125 ppm STEL; 545 mg/m3 STEL
		Brazil	78 ppm TWA; 340 mg/m3 TWA
0000108-65-6	Propylene glycol monomethyl	OSHA	No Established Limit
	ether acetate	ACGIH	No Established Limit
		NIOSH	No Established Limit
		Supplier	No Established Limit
		OHSA, CAN	50 ppm TWA; 270 mg/m3 TWA
		Mexico	No Established Limit
		Brazil	No Established Limit
0001317–65–3	Limestone	OSHA	15 mg/m3 TWA (total dust); 5 mg/m3 TWA
			(respirable fraction)
		ACGIH	No Established Limit
		NIOSH	10 mg/m3 TWA (total dust); 5 mg/m3 TWA (respirable dust)
		Supplier	No Established Limit
		OHSA, CAN	No Established Limit
		Mexico	10 mg/m3 TWA20 mg/m3 STEL
		Brazil	No Established Limit
0001330–20–7 Xy	Xylenes (o–, m–, p– isomers)	OSHA	100 ppm TWA; 435 mg/m3 TWA150 ppm STEL; 655 mg/m3 STEL
		ACGIH	100 ppm TWA150 ppm STEL
		NIOSH	No Established Limit
		Supplier	No Established Limit
		OHSA, CAN	100 ppm TWA150 ppm STEL
		Mexico	100 ppm TWA; 435 mg/m3 TWA150 ppm STEL; 655 mg/m3 STEL
		Brazil	78 ppm TWA; 340 mg/m3 TWA
0007727–43–7	Barium sulfate	OSHA	15 mg/m3 TWA (total dust); 5 mg/m3 TWA (respirable fraction)
		ACGIH	10 mg/m3 TWA
		NIOSH	10 mg/m3 TWA (total dust); 5 mg/m3 TWA (respirable dust)
		Supplier	No Established Limit
		OHSA, CAN	10 mg/m3 TWA (total dust)
		Mexico	No Established Limit
		Brazil	No Established Limit
0014808–60–7	Quartz	OSHA	No Established Limit
		ACGIH	0.025 mg/m3 TWA (respirable fraction)
		NIOSH	0.05 mg/m3 TWA (respirable dust)50 mg/m3 IDLH (respirable dust)
		Supplier	No Established Limit
		OHSA, CAN	0.10 mg/m3 TWA (designated substance regulatic respirable)0.10 mg/m3 TWA (respirable fraction)
		Mexico	0.1 mg/m3 TWA (respirable fraction)
		Brazil	No Established Limit
0064742-95-6	Petroleum naphtha	OSHA	No Established Limit

NIOSH	No Established Limit
Supplier	No Established Limit
OHSA, CAN	No Established Limit
Mexico	No Established Limit
Brazil	No Established Limit

	Health Da	ata	
CAS No.	Ingredient	Source	Value
0000095-63-6	1,2,4–Trimethyl benzene	NIOSH	No Established Limit
0000100-41-4	Benzene, ethyl-	NIOSH	Eye skin
	Propylene glycol monomethyl ether acetate	NIOSH	No Established Limit
0001317-65-3	Limestone	NIOSH	Eye and skin irritation Physical irritation
0001330–20–7	Xylenes (o–, m–, p– isomers)		Central nervous system depressant; respiratory and eye irritation
0007727-43-7	Barium sulfate	NIOSH	Eye nose
0014808-60-7	Quartz	NIOSH	Chronic lung disease (silicosis)
0064742-95-6	Petroleum naphtha	NIOSH	No Established Limit

Carcinogen Data				
CAS No.	Ingredient	Source	Value	
0000095–63–6	5–63–6 1,2,4–Trimethyl OSHA		Select Carcinogen: No	
	benzene	NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	
0000100-41-4	Benzene, ethyl–	OSHA	Select Carcinogen: Yes	
		NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: Yes; Group 3: No; Group 4: No;	
	Propylene glycol	OSHA	Select Carcinogen: No	
	monomethyl ether	NTP	Known: No; Suspected: No	
	acetate	IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	
0001317–65–3	Limestone	OSHA	Select Carcinogen: No	
		NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	
0001330–20–7	isomers)	OSHA	Select Carcinogen: No	
		NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: Yes; Group 4: No;	
0007727–43–7	N	OSHA	Select Carcinogen: No	
		NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	
0014808–60–7	Quartz	OSHA	Select Carcinogen: Yes	
	· · · ·	NTP	Known: Yes; Suspected: No	
		IARC	Group 1: Yes; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	
0064742–95–6	Petroleum naphtha	OSHA	Select Carcinogen: No	
		NTP	Known: No; Suspected: No	
		IARC	Group 1: No; Group 2a: No; Group 2b: No; Group 3: No; Group 4: No;	

Respiratory

Select equipment to provide protection from the ingredients listed in Section 3 of this document. Ensure fresh air entry during application and drying. If you experience eye watering, headache or dizziness or if air monitoring demonstrates dust, vapor, or mist levels are above applicable limits, wear an appropriate, properly fitted respirator (NIOSH approved) during and after application. Follow respirator manufacturer's

	directions for respirator use. FOR USERS OF 3M RESPIRATORY PROTECTION ONLY: For information and assistance on 3M occupational health and safety products, call OH&ESD Technical Service toll free in U.S.A. 1–800–243–4630, in Canada call 1–800–267–4414. Please do not contact these numbers regarding other manufacturer's respiratory protection products. 3M does not endorse the accuracy of the information contained in this Material Safety Data Sheet.
Eyes	Do not get in eyes. Protective equipment should be selected to provide protection from exposure to the chemicals listed in Section 3 of this document. Depending on the site-specific condition of use, safety glasses, chemical goggles, and/or head and face protection may be required to prevent contact. The equipment must be thouroughly cleaned, or discarded after each use. Protective equipment should be selected to provide protection from exposure to the chemicals listed in Section 3 of this document. Depending on the site-specific conditions of use, safety glasses, chemical goggles, and/or head and face protection may be required to prevent contact. The equipment must be thoroughly cleaned, or discarded after each use.
Skin	Protective equipment should be selected to provide protection from exposure to the chemicals listed in Section 3 of this document. Depending on the site–specific conditions of use, protective gloves, apron, boots, head and face protection may be required to prevent contact. The equipment must be thoroughly cleaned, or discarded after each use.
Engineering Controls	Prevent build-up of vapors by opening all windows and doors to achieve cross-ventilation.
Other Work Practices	Emergency eye wash fountains and safety showers should be available in the immediate vicinity of any potential exposure. Use good personal hygiene practices. Wash hands before eating, drinking, using toilet facilities, etc. Promptly remove soiled clothing and wash clothing thoroughly before reuse. Shower after work using plenty of soap and water.

	9. Physical and chemical properties
Physical State	Liquid Coloured
рН	No Established Limit
Specific Gravity	1.34
Boiling Point F	220
Vapor Density	Heavier than air
VOC %	Refer to the Technical Data Sheet or label where information is available.
Evaporation Rate	Slower than ether
	10. Stability and reactivity

General	This product is stable and hazardous polymerization will not occur. Not sensitive to mechanical impact. Excessive heat and fumes generation can occur if improperly handled.
Incompatible Materials	Strong oxidizing agents.
Hazardous Decompostion	May produce hazardous fumes when heated to decomposition as in welding. Fumes may produce Carbon Dioxide and Carbon Monoxide.

11. Toxicological information						
Ingredient	Oral LD50, mg/kg	Skin LD50, mg/kg	Inhalation Vapor LD50, mg/L/4hr			
1,2,4–Trimethyl benzene – (0000095–63–6)	3,400.00, Rat – Category: 5	3,160.00, Rabbit - Category: 5				
Benzene, ethyl- – (0000100-41-4)	3,500.00, Rat – Category: 5	15,354.00, Rabbit – Category: NA	17.20, Rat – Category: 4			
Propylene glycol monomethyl ether acetate – (0000108–65–6)	8,532.00, Rat – Category: NA	5,000.00, Rabbit - Category: 5				
Limestone – (0001317–65–3)						
Xylenes (o–, m–, p– isomers) – (0001330–20–7)	4,300.00, Rat – Category: 5	1,700.00, Rabbit - Category: 4	29.08, rat – Category: NA			
Barium sulfate – (0007727–43–7)						
Quartz - (0014808-60-7)	500.00, Rat – Category: 4					

Petroleum naphtha – (0064742–95–6)	8,400.00, Rat – Category: NA	2,000.00, Rabbit - Category: 4	5.20, Rat – Category: 3	
------------------------------------	---------------------------------	-----------------------------------	----------------------------	--

NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal. No additional information provided for this product. See Sections 8 and 11 for chemical specific data.

12. Ecological information

Not Defined

General

No additional information provided for this product. See Sections 8 and 11 for chemical specific data.

13. Disposal considerations

Dispose of in accordance with local, state and federal regulations. (Also reference RCRA information in Section 15 if listed).

	14. Transpo	ort information			
DOT (Domestic Surface Transportation)		IMO / IMDG (Oce	IMO / IMDG (Ocean Transportation)		
DOT Proper Shipping Name	PAINT	IMDG Proper Shipping Name	PAINT		
DOT Hazard Class	3	IMDG Hazard Class	3 – Flammable and Combustible liquid		
UN / NA Number	UN 1263	UN / NA Number	UN 1263		
DOT Packing Group	III	IMDG Packing Group	III		
CERCLA/DOT RQ	67 gal. / 751 lbs.	System Reference Code	1		
	15. Regulate	ory information			
Regulatory Overview	selected regulations a on the TSCA (Toxic Si listed on the TSCA Inv	Section 15 is not intended to b re represented. All ingredients ubstance Control Act) Inventory rentory.	of this product are listed		
WHMIS Classification	9999				
DOT Marine Pollutants (No Product Ingr					
DOT Severe Marine Po (No Product Ingre					
EPCRA 311/312 Chem	icals and RQs (>.1%) :				
Benzene,	ethyl- (1000 lb final RQ; 45	i4 kg final RQ)			
BUTYL A	CETATE (5000 lb final RQ;	2270 kg final RQ)			
Xylenes (o-, m-, p- isomers) (100 lb	final RQ; 45.4 kg final RQ)			
EPCRA 302 Extremely (No Product Ingre					
EPCRA 313 Toxic Che	micals (>.1%) :				
1,2,4–Tri	methyl benzene				
Benzene,	ethyl–				
Xylenes (o–, m–, p– isomers)				
Mass RTK Substances	(>1%) :				
1,2,4–Tri	methyl benzene				
Barium si	ulfate				
Benzene,	ethyl–				
Limeston	e				
	o–, m–, p– isomers)				
Mass Extraordinarily Ha	az Sub (>.01%) :				
Quartz					

Silica, cristobalite Penn RTK Substances (>1%) : 1,2,4-Trimethyl benzene Barium sulfate Benzene, ethyl-Limestone Xylenes (o-, m-, p- isomers) Penn Special Hazardous Substances (>.01%) : (No Product Ingredients Listed) Rhode Island Hazardous Substances (>.1%) : Benzene, ethyl-Kaolin Limestone BUTYL ACETATE Quartz Xylenes (o-, m-, p- isomers) RCRA Status (%): N.J. RTK Substances (>1%) : 1,2,4-Trimethyl benzene Barium sulfate Benzene, ethyl-Limestone Xylenes (o-, m-, p- isomers) N.J. Special Hazardous Substances (>.01%) : Benzene, ethyl-Isobutyl alcohol **BUTYL ACETATE** Quartz Silica, cristobalite Xylenes (o-, m-, p- isomers) N.J. Env. Hazardous Substances (>.1%) : 1,2,4-Trimethyl benzene Benzene, ethyl-Xylenes (o-, m-, p- isomers) Proposition 65 – Carcinogens (>0%): Benzene, ethyl-Nickel Quartz Proposition 65 – Female Repro Toxins (>0%): (No Product Ingredients Listed) Proposition 65 – Male Repro Toxins (>0%): (No Product Ingredients Listed) Proposition 65 – Developmental Toxins (>0%): (No Product Ingredients Listed)

Risk Phrases: R20/21: Harmful by inhalation and in contact with skin. R36/38: Irritating to eyes and skin. R52/53: Harmful to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

16. Other information

The information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind, expressed or implied, is made with respect to the information contained herein. We accept no responsibility and disclaim all liability for any harmful effects which may be caused by exposure to our products. Customers/users of this product must comply with all applicable health and safety laws, regulations, and orders.